

## ECS Configuration Change Request

Page 1 of

Page(s)

<b>1. Originator</b> Robert Cole	<b>2. Log Date:</b> <b>05/29/03</b>	<b>3. CCR #:</b> <b>03-0386</b>	<b>4. Rev:</b> —	<b>5. Tel:</b> 301.925.0799	<b>6. Rm #:</b> 2110C	<b>7. Dept.</b> SE/HW
<b>8. CCR Title:</b> Reconfigure LPDAAC and LaRC Datapools After Storage Array Failure						
<b>9. Originator Signature/Date</b> Robert Cole /s/ 05/29/03			<b>10. Class</b> II	<b>11. Type:</b> CCR	<b>12. Need Date:</b> 6/15/03	
<b>13. Office Manager Signature/Date</b> James Mather /s/ 05/29/03			<b>14. Category of Change:</b> Update ECS Baseline Doc.		<b>15. Priority:</b> (If "Emergency" fill in Block 27). Routine	
<b>16. Documentation/Drawings Impacted</b> (Review and submit checklist): See attached sheet			<b>17. Schedule Impact:</b>		<b>18. CI(s) Affected:</b> SANHW	
<b>19. Release Affected by this Change:</b> N/A		<b>20. Date due to Customer:</b>		<b>21. Estimated Cost:</b> None - Under 100K		
<b>22. Source Reference:</b> <input checked="" type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other: ECSed37539						
<b>23. Problem: (use additional Sheets if necessary)</b> Recent storage array failures at LPDAAC and LaRC have necessitated the replacement of the 9176 storage arrays at those sites with D178 storage arrays. This replacement has required the upgrade of RDAC to version 08.30.02.00 and Santricity to version 08.30.G2.00.						
<b>24. Proposed Solution: (use additional sheets if necessary)</b> Baseline the COTS software upgrades and storage array reconfiguration following the replacement.						
<b>25. Alternate Solution: (use additional sheets if necessary)</b> none						
<b>26. Consequences if Change(s) are not approved: (use additional sheets if necessary)</b> Inaccurate baseline						
<b>27. Justification for Emergency (If Block 15 is "Emergency"):</b>						
<b>28. Site(s) Affected:</b> <input type="checkbox"/> EDF <input type="checkbox"/> PVC <input type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
<b>29. Board Comments:</b>				<b>30. Work Assigned To:</b>	<b>31. CCR Closed Date:</b>	
<b>32. EDF/SCDV CCB Chair (Sign/Date):</b>		<b>Disposition:</b> Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
<b>33. M&amp;O CCB Chair (Sign/Date):</b> Gary Gavigan /s/ 6/3/03		<b>Disposition:</b> <span style="border: 1px solid red; color: red;">Approved</span> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
<b>34. ECS CCB Chair (Sign/Date):</b>		<b>Disposition:</b> Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS				

## ADDITIONAL SHEET

**CCR #:** 03-0386

**Rev:** — **Originator:**

**Telephone:**

**Office:**

**Title of Change:**

921-TDE-002  
921-TDE-003  
921-TDL-002  
921-TDL-003  
920-TDE-001  
920-TDL-002  
920-TDE-002  
920-TDL-002  
922-TDE-044  
922-TDL-044  
910-TDA-003  
910-TDA-023